



TEL:....(+47) 67 03 00 00

E-mail:..aim@avinor.no

NORWAY

**AERONAUTICAL INFORMATION
MANAGEMENT**

P.O. BOX 150

NO-2061 GARDERMOEN

AIP SUP

08/23

28 APR 2023

08

LPV-MINIMA SUSPENDERT NORD AV 70N

Erstatter NOTAM

*A/1217/23, A/1218/23, E/1619/23, A/2431/23,
A/2432/23, A/2434/23, A/2433/23, A/2435/23*

LPV-minima er suspendert på følgende prosedyrer
grunnet utfordringer knyttet til kontinuiteten i EGNOS-
signalet nord av 70N:

LPV MINIMA SUSPENDED NORTH OF 70N

Replaces NOTAM

*A/1217/23, A/1218/23, E/1619/23, A/2431/23,
A/2432/23, A/2434/23, A/2433/23, A/2435/23*

LPV minima for the following procedures are suspended
due to continuity issues related to the EGNOS signal
north of 70N:

ENBS RNP RWY 03
ENBS RNP RWY 21
ENBV RNP RWY 06
ENBV RNP RWY 24
ENHK RNP RWY 11
ENHK RNP RWY 29
ENKR RNP RWY 05
ENKR RNP RWY 23
ENMH RNP RWY 17
ENMH RNP RWY 35
ENNA RNP X RWY 16 (LPV only)
ENNA RNP X RWY 34 (LPV only)
ENSS RNP RWY 15
ENSS RNP Z RWY 33

Samtlige prosedyrer er gjenstand for kontrollflyging
samt godkjenning fra Luftfartstilsynet før de benyttes
operativt.

All of these procedures are subject to flight validation
and CAA approval prior to operational use.

~ Slutt ~

~ End ~