

TEL:.....+47 67 03 00 00

E-mail:.....aim@avinor.no



# AVINOR

## NORWAY

AERONAUTICAL INFORMATION  
MANAGEMENT  
P.O. BOX 150  
NO-2061 GARDERMOEN

**AIP AIRAC SUP**  
**32/2024**  
**EFF 28 NOV 2024**

**Publication date: 11 OCT 2024**

### LPV-MINIMA SUSPENDERT NORD AV 70N

*Erstatter AIP SUP 08/2023*

LPV-minima er suspendert på følgende prosedyrer grunnet utfordringer knyttet til kontinuiteten i EGNOS-signalet nord av 70N:

- ENBS RNP RWY 03
- ENBS RNP RWY 21
- ENBV RNP RWY 06
- ENBV RNP RWY 24
- ENHF RNP Z RWY 04
- ENHF RNP Z RWY 22
- ENHK RNP RWY 11
- ENHK RNP RWY 29
- ENKR RNP RWY 05
- ENKR RNP RWY 23
- ENMH RNP RWY 17
- ENMH RNP RWY 35
- ENNA RNP X RWY 16 (LPV only)
- ENNA RNP X RWY 34 (LPV only)
- ENSS RNP RWY 15
- ENSS RNP Z RWY 33

Samtlige prosedyrer er gjenstand for kontrollflyging samt godkjenning fra Luftfartstilsynet før de benyttes operativt.

- Slutt -

### LPV MINIMA SUSPENDED NORTH OF 70N

*Replaces AIP SUP 08/2023*

LPV minima for the following procedures are suspended due to continuity issues related to the EGNOS signal north of 70N:

- ENBS RNP RWY 03
- ENBS RNP RWY 21
- ENBV RNP RWY 06
- ENBV RNP RWY 24
- ENHF RNP Z RWY 04
- ENHF RNP Z RWY 22
- ENHK RNP RWY 11
- ENHK RNP RWY 29
- ENKR RNP RWY 05
- ENKR RNP RWY 23
- ENMH RNP RWY 17
- ENMH RNP RWY 35
- ENNA RNP X RWY 16 (LPV only)
- ENNA RNP X RWY 34 (LPV only)
- ENSS RNP RWY 15
- ENSS RNP Z RWY 33

All of these procedures are subject to flight validation and CAA approval prior to operational use.

- End -