

TEL:.....+47 67 03 00 00

E-mail:.....aim@avinor.no



**AERONAUTICAL INFORMATION
MANAGEMENT
P.O. BOX 150
NO-2061 GARDERMOEN**

**AIP SUP
10/2025
04 MAR 2025**

ENGM – Skilt for avgang fra kryss mangler

Erstatter NOTAM A6761/24

Skilt for avgang fra kryss for redusert (alternativ) avgang PSN TWY A5 og TWY C2 mangler inntil videre. Se AIP AD 2 ENGM AD 2.13 for kunngjort banelengde.

- Slutt -

ENGM – Intersection take-off sign is missing

Replaces NOTAM A6761/24

Intersection take-off sign for reduced (alternate) take-off PSN TWY A5 and TWY C2 is missing UFN. See AIP AD 2 ENGM AD 2.13 for declared distance.

- End -