

TEL:.....+47 67 03 00 00

E-mail:.....aim@avinor.no



AVINOR NORWAY

AERONAUTICAL INFORMATION
MANAGEMENT
P.O. BOX 150
NO-2061 GARDERMOEN

AIP SUP
45/2025
18 JUL 2025

ENGM - Skilt for avgang fra kryss mangler

Erstatter AIP SUP 10/2025

Skilt for avgang fra kryss for redusert (alternativ) avgang PSN TWY A5 mangler inntil videre. Se AIP AD 2 ENGM AD 2.13 for kunngjort banelengde.

- Slutt -

ENGM - Intersection take-off sign is missing

Replaces AIP SUP 10/2025

Intersection take-off sign for reduce (alternate) take-off PSN TWY A5 is missing UFN. See AIP AD 2 ENGM AD 2.13 for declared distance.

- End -