

TEL:.....(+47) 815 30 550

E-mail:.aim@avinor.no

**AVINOR**
NORWAY

**AERONAUTICAL INFORMATION
MANAGEMENT
P.O. BOX 150
NO-2061 GARDERMOEN**

AIP
AMDT 04/18
21 JUN 2018

AIRAC

Publiseringsdato: 10 MAY 2018

Publication date: 10 MAY 2018

Ikrafttredelse: 21 JUN 2018

Effective date: 21 JUN 2018

Principal changes included in this AMDT:

Brief indication of the subjects affected by the AMDT:

Part	AIRAC change(s):	AIP page(s)
GEN		
2.4	New: ENUN* - Aasta Hansteen, ENQM* - Martin Linge A, ENQL* - Martin Linge B	GEN 2.4-1/3/4/5
ENR		
2.2	New HTZ: Aasta Hansteen HTZ and Martin Linge HTZ New installations offshore: ENUN - Aasta Hansteen, ENQM - Martin Linge A, ENQL - Martin Linge B Some Special Reporting Points withdrawn on route KY955 and KY956. Norway ACC Sector 8 and 10 realigned	ENR 2.2-6/7/8/9/ 10/11/12/13/14/19/ 20
3.4	KY955 and KY956 realigned	ENR 3.4-13/14
4.4	New PKT: ABRIR, BEGOG, EVGES, OSDOD, UVSOL Revised PKT: AKOKU, INVAL, ODNOS Withdrawn PKT: LIRPU, OLADO	ENR 4.4-1/2/4/7/9/ 11/14/15/21
5.5	Airwork D2 renamed Airwork F and lateral limits revised. Kopparen 1: Editorials	ENR 5.5-1/4
6.2	Sectorization charts revised.	6.2-23/25
6.4	Helicopter charts: ENQM/ENUN HTZ and helideck introduced. ENQL helideck revised. Helicopter Reporting Points replaced with ICAO reporting points. Helicopter Traffic Zones charts revised design and content. Offshore Helicopter Area - Northern Norway -chart introduced.	6.4-1/3/4/5/6/7/9
6.6	Airwork D2 renamed Airwork F and lateral limits revised.	6.6-1
AD		
ENxx	ATCSMAC, Radar Vectoring Chart or Vectoring Chart withdrawn from AIP altogether. Affects ENAN, ENAL, ENAT, ENBO, ENCN, ENDU, ENEV, ENHF, ENGM, ENKB, ENKR, ENNA, ENRO, ENVA and ENZV.	ENAL 1-8, 4-1/2/3, ENAT 1-8, 4-1/2 ENBO 1-10, 4-15 ENCN 1-9, 4-1/2 ENDU 1-9, 4-1 ENEV 1-9, 4-1/2 ENGM 1-19, 4-1/2 ENKB 1-8, 4-1/2/3 ENKR 1-8, 4-1/2 ENNA 1-8, 4-1/2 ENRO 1-8, 4-1/2 ENVA 1-14, 4-1/2 ENZV 1-14, 4-1/2
ENAT	TMA/TIA chart revised.	ENAT 7-1
ENBR	HELI SID RWY 17/35 editorials. STAR RWY 17 Editorials.	ENBR 4-19/23
ENBS	AD 2.3 Opening hours.	ENBS 1-1
ENEV	AD 2.8 ACFT stands re-surveyed, one new. AD 2.12 RWY end and surface end resurveyed. RWY DMN and strip CHG. RESA undershoot added. AD 2.13 All declared distances CHG. AD 2.19 LOC 17 resurveyed. ADC revised-	ENEV 1-2/4/5/6, 2-1

ENKR	ADC revised.	ENKR 2-1
ENNM	AD 2.18 VDF restrictions changed.	ENNM 1-5
ENHF	TMA/TIA chart revised.	ENHF 7-1
ENHK	TMA/TIA chart revised.	ENHK 7-1
ENNA	TMA/TIA chart revised.	ENNA 7-1
ENRA	AD 2.8 ACFT stand 2 position updated. Helicopter stands 1 and 2 added. AD 2.12 RWY end RWY 14 coordinates updated.	ENRA 1-2/4
ENML	LOC Z RWY 25 and VAC revised.	ENML 5-9, 6-1
ENGM	AD 2.4 Change of frequency for de-icing. AD 2.12 CWY revised RWY 19L. AD 2.14 RWY LGT revised. AD 2.18 Change of frequencies for Gardermoen Delivery and Ground. All ground, SID, IAC and VAC revised with new FREQ.	ENGM 1-2/4/5/6, 2-1 to 2-11, 4-3 to 4-23, 5-1 to 5-29, 6-1
ENSG	ADC revised.	ENSG 2-1
ENSR	AD 2.2 ATS and AD 2.6 Fire and rescue: Changed HRS of service	ENSR 1-1/2
ENRY	AD 2.2, AD 2.8, AD 2.9, AD 2.15 and AD 2.19 Changed category to CAT I. AD 2.3 Changed ATS hours of service. AD 2.12 Changed type of RAG for RWY 12. AD 2.23 Change of text regarding wildlife hazard.	ENRY 1-1/3/4/5/6/7
ENTO	SID/STAR and IAC revised.	ENTO 4-3/7/11, 5-1/3/5/7/9/11
ENVD	Opening hours	ENVD 1-1/2
ENSS	AD 2.3 Changed hours of service for ATS and de-icing. AD 2.9 Added RMK RWY end LGT	ENSS 1-1/2

Part NON AIRAC change(s) AIP page(s)

Pages affected by page overflow and no actual corrections may not be listed

GEN

0.2	Update date	GEN 0.2-1
0.4	Checklist revised	GEN 0.4-1 to 12
2.2	New: FAB, GRS, IMS. Removed: GCA and LORAN. Editorials.	GEN 2.2-8/10/12/13
3.2	Removed ATCSMAC. Editorials list AVBL charts.	GEN 3.2-1/2/3
3.4	Editorials	GEN 3.4-1
3.5	Para 3 ENRY: MET-report no longer provided. Hours of service updated.	GEN 3.5-11

ENR

1.6	Para 3: Editorials. Para 4.5 Removed. Para 4.6 Removed	ENR 1.6-3/5/6
1.8	Para 5: Editorials	ENR 1.8-15

AD

1.5	Date of EU certification updated for several AD	AD 1.5-1/2
-----	---	------------

ENBR	2.23 Editorials	ENBR 1-14
ENBO	AD 2.5 Tourist information at AD withdrawn. AD 2.9 RWY end marking withdrawn. AD 2.12 Information on RAG updated	ENBO 1-2/3/5
ENBS	AD 2.9 editorials. ADC: RWY turn pads	ENBS 1-2, 2-1
ENFL	AD 2.9 Editorials, AD 2.22 Editorials	ENFL 1-3/7
ENHF	AD 2.9 RWY end marking withdrawn	ENHF 1-2
ENEV	AD 2.17 duplications removed. Shifting of pages	ENEV 1-6

ENHV	AD 2.9 RWY end marking withdrawn. RWY LGT updated	ENHV1-2
ENML	AD 2.9 RWY end marking withdrawn. Reference to AOC-B charts removed.	ENML 1-3/9, ENML 3-5
ENGM	AD 2.3, 2.5 - 2.7, 2.9, 2.11, 2.13, 2.15, 2.17, 2.19 - 2.21 Editorials. AD 2.24 ATCSMAC chart withdrawn.	ENGM 1-1/2/3/ 4/5/6/7/9-13/ 15-19, 4-1/2
ENRO	AD 2.3 Editorials	ENRO 1-1
ENSB	2.2 New admin name	ENSB 1-1
ENSA	2.14 PLASI RWY 04, RMK deleted. ADC revised.	ENSA 1-4, 2-1
ENSK	VAC revised.	ENSK 6-1
ENSG	2.8, 2.9, 2.14 and 2.23 Editorials	ENSG 1-2/4/7
ENVD	2.9 RWY end marking and LGT	ENVD 1-2
ENSS	AD 2.5 Changed opening time for tourist office.	ENSS 1-2

Denne rettelse omfatter innholdet i følgende NOTAM:

AV-0310/18, AV-0365/18, AV-0416/18, AV-0584/18

This amendment incorporates information in the following NOTAM:

A-0790/18, A-0948/18, A-1022/18, A-1522/18

This amendment incorporates information in the following AIP SUP:

12/18

- Slutt / End -