

TEL:.....+47 67 03 00 00

E-mail:.....aim@avinor.no



**AERONAUTICAL INFORMATION
MANAGEMENT
P.O. BOX 150
NO-2061 GARDERMOEN**

**AIP SUP
21/2025
04 APR 2025**

**ENEV – Sekvens blinkende lys ute av drift på Evenes
lufthavn, Harstad, Narvik**

Erstatter NOTAM A1919/25

Sekvens blinkende lys RWY 35 ute av drift UFN.

- Slutt -

**ENEV – Sequenced flashing lights unserviceable at Evenes
airport, Harstad, Narvik**

Replaces NOTAM A1919/25

Sequenced flashing lights RWY 35 unserviceable UFN.

- End -