

TEL:.....(+47) 815 30 550

E-mail:.aim@avinor.no



# AVINOR

## NORWAY

AERONAUTICAL INFORMATION  
MANAGEMENT  
P.O. BOX 150  
NO-2061 GARDERMOEN

**AIP**  
**AMDT 05/18**  
**13 SEP 2018**

**AIRAC**

Publiseringsdato: 02 AUG 2018

Publication date: 02 AUG 2018

Ikrafttredelse: 13 SEP 2018

Effective date: 13 SEP 2018

Principal changes included in this AMDT:

*Brief indication of the subjects affected by the AMDT:*

| <b>Part</b> | <b>AIRAC change(s):</b>   | <b>AIP page(s)</b>   |
|-------------|---|--|
| GEN         |   |  |
| 1.1         | Norwegian Air Sports Authority established  | GEN 1.1-1  |
| 2.2         | Heidrun B PSN and Heidrun TIZ updated   | ENR 2.2-8/11   |
| 3.3         | 4.1.4.2/5: Removed Norwegian phraseology  | GEN 3.3-5  |
| 3.5         | Ekofisk: New designator. ENTO New MET EQPT  | GEN 3.5-4/12   |
| ENR         | GIMUX replaced by ULVIR. TOKLA and XEGRO added FRA RMK  | ENR 4.4-7/19/20/22   |
| 1.7         | QNH setting areas realigned, editorials   | ENR 1.7-6/8/9/10   |
| 2.2         | Para 6: ACC sector 24 adjusted. Sector 27 established   | ENR 2.2-24/25  |
| 4.4         | Para 4.4.1:<br>GIMUX replaced by ULVIR. TOKLA and XEGRO added with FRA RMK<br>Para 4.4.2:<br>ENBN BINTU, DOREP, RAKOS withdrawn. BN408, BN420, BN421, BN422 new   | ENR 4.4-7/19/20/22<br>ENR 4.4-27                                       |
| 5.1         | En D257 AWES Lista established  | ENR 5.1-6  |
| 6-2         | Enroute chart - Northern Norway/Svalbard Area: KY970 withdrawn<br>Sectorization charts: Sector 8/10 revised. Sector 27 established.   | ENR 6.2-7/9<br>ENR 6.2-23/25   |
| 6-4         | Offshore Helicopter Area charts: Editorials<br>QNH setting areas, Haltenbanken: Areas realigned   | ENR 6.4-1/2<br>ENR 6.4-10  |
| AD          |   |  |
| ENAT        | AD 2.3 and 2.4 Opening hours updated. AD 2.9 RWY end marking removed.<br>AD 2.14 MEHT CHG   | ENAT 1-1/2/3/5   |
| ENBV        | AD 2.12 RESA undershoot updated   | ENBV 1-4   |
| ENBO        | AD 2.6 CHG HR of OPER. AD 2.20 para 3 and 4 on push-back and de-ice procedures<br>new. AD 2.16 TLOF/FATO established. ADC revised   | ENBO 1-2/6/7/8, 2-1  |
| ENBN        | AD 2.2, 2.10, 2.12, 2.13, 2.14, 2.19 RWY ID changed. AD 2.8 PSN on ACFT and<br>HELI stands revised. AD 2.14 MEHT, PLASI angle and Screen Height changed. All<br>relevant charts updated with CHG RWY ID. PLASI relocated. PROC LOC RWY 04<br>withdrawn. | ENBN 1-1/2/3/4/6/7/8<br>2-1, 3-1/3, 4-1/3,<br>5-1 through 5-14,<br>6-1 |
| ENGM        | Ground charts revised   | ENGM 2-1/2/3/4/5/8/9/11  |
| ENEV        | SID RWY 17/35 revised. SID/STAR RWY 17/35 renumbered.   | ENEV 4-1 through 10  |
| ENHK        | AD 2.2 Status RWY 11 and 29 updated to precision. AD 2.9 RWY marking and LGT<br>updated.  | ENHK 1-1/2   |
| ENHV        | AD 2.6: HR of SER fire and rescue   | ENHV 1-2   |
| ENKR        | AD 2.2 HR of SER, AD 2.8: ELEV, AD 2.13: ALTN DIST, AD 2.14: RWY LGT,<br>AD 2.17 HR of SER  | ENKR 1-1/2/4/5   |
| ENMH        | AD 2.14 RWY end WBAR removed  | ENMH 1-4   |



|      |   |                          |
|------|---|--------------------------|
| ENNA | AD 2.19 TACAN BNK ELEV updated  | ENNA 1-6                 |
| ENMH | AD 2.2 REF in RMK relocated. Editorials. AD 2.6 and AD 2.7 editorials. AD 2.20 para 2 relocated from AD 2.23, renumbering   | ENMH 1-1/2/6/7           |
| ENGM | AD 2.9 Editorials   | ENGM 1-3                 |
| ENRY | AD 2.19 TACAN RYG ELEV updated  | ENRY 1-6                 |
| ENSD | AD 2.2 and AD 2.3 Editorials. AD 2.15 switch-over time updated. AD 2.20 and AD 2.23 editorials. VAC editorials.   | ENSD 1-1/5/6/7, 6-1      |
| ENTO | AD 2.6, 2.7, 2.8, 2.9, 2.11, 2.15, 2.20, 2.21, 2.23 Editorials  | ENTO 1-2/3/5/6/7/11      |
| ENSG | AD 2.2, AD, 2.3, AD 2.6, AD 2.7 editorials. AD 2.23 para 2 relocated to AD 2.20. ADC editorials   | ENSG 1-1/2/6/8, 2-1      |
| ENZV | AD 2.18 Call-sign ENZV APP changed to Sola Approach. AD 2.22 Wording with “radar” changed to “surveillance”. VAC, TMA/TIA chart revised.  | ENZV 1-7/11/12, 6-1, 7-1 |
| ENSO | TMA/TIA chart revised   | ENSO 7-1                 |
| ENSK | AD 2.2 REF in RMK removed. Editorials. AD 2.4, AD 2.6 and AD 2.7 editorials. AD 2.20 para 2 relocated from AD 2.23, renumbering. AD 2.23: Differences from Annex 14 SARPS, VAC revised. | ENSK 1-1/2/7/8, 6-1      |
| ENSR | AD 2.2, AD 2.3, AD 2.6, AD 2.7 and AD 2.9 Editorials. AD 2.23 para 2 relocated to AD 2.20 para 2  | ENSR 1-1/2/6/7           |
| ENAL | AD 2.24 Renumbering of SID/STAR charts  | ENAL 1-7                 |
| ENVR | AD 3.2, 3.3, 3.4, 3.6, 3.11, 3.12, 3.17 and 3.22: Editorials  | ENVR 1-1/2/3/4/5         |

**Denne rettelse omfatter innholdet i følgende NOTAM:**

AV-0175/18, AV-0453/18, AV-0620/18, AV-0707/18, AV-0765/18, AV-0773/18, AV-0841/18, AV-0842/18, AV-0844/18, AV-0846/18

**This amendment incorporates information in the following NOTAM:**

A-0521/18, A-1039/18, A-1177/18, A-1623/18, A-1039/18, A-1785/18, A1966/18, A-2142/18, A-2143/18, A-2145/18, A-2147/18

**This amendment incorporates information in the following AIP SUP:**

13/18

- Slutt / End -